

# CORNER RECORD


# COUNTY OF PLACER, CALIFORNIA

City of Unincorporated

Document Number 20140074

Brief Legal Description Centerline Area 'K' at Virginiatown Road, 33 PM 113

PLS Job No. 833



S. 9

T. 12 N

R. 7 E

## CORNER TYPE

☐ Government Corner ☐ Control  
☐ Meander ☒ Property  
☐ Rancho ☐ Other  
 Date of Survey 4/16/14

## COORDINATES

(Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner ---

☒ Left as found ☐ Found and tagged ☐ Established ☐ Reestablished ☐ Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish corner:

Found 3/4" pipe w/plug L.S. 4715 as shown on 33 PM 113

A description of the physical condition of the monument as found and as set or reset:

Monument was found in good condition, at surface, prior to waterline construction.

Will have to be revisited after construction to determine status.

## SURVEYOR'S STATEMENT


This Corner Record was prepared by me or under my direction

in conformance with the Professional Land Surveyors' Act

on May 30, 20 14

Signed Richard A Marino

L.S. or R.C.E. Number 6376 Signed October 25, 2016




## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received \_\_\_\_\_ 20 \_\_\_\_\_

and examined and filed November 12 2016 20 \_\_\_\_\_



Signed Leslie Amberry Title County Surveyor

L.S. or R.C.E. Number 6584



County Surveyor's Comment \_\_\_\_\_





NOTE:  
THIS CORNER RECORD REPRESENTS  
THE AS FOUND LOCATION OF THE  
MONUMENT SHOWN HEREON. NO  
SURVEY HAS BEEN MADE TO  
DETERMINE THE RELATIONSHIP OF THE  
FOUND MONUMENT TO ANY  
SURROUNDING RECORD MAPS.